ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra

Street ID	Street Name	Significant Landmark
W0327, W0274, I0246, W0331	Lakshmi Sagar Lyt North Side, 2nd Crs, 2nd Crs, Maheshwari Nagar, NA, Lakshmi Sagar Lyt 6th Crs	Byrappa Garden

Segment No.	Total Length (m)
10/C-W0327/S105511	97.72

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	36.86	77.552821	13.058004	77.552810	13.058337	I0246	W0274
2	60.86	77.552623	13.057988	77.552604	13.058538	I0246	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Byrappa Garden in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone	900000	2016

Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	

Tender	Work Details	Job No. / Work Code
Not a Tender	Improvements to Roads and Drains at Byrappa Garden in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone	010-16-000038

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/94/2016-17	05/08/2016	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
05/08/2016	04/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00

Phone No.	E-Mail ID

9449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
1		MADHAV RAO
Date of Inspection	**Remarks**	
05/12/2016	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0327, W0274, I0246, W0331

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	05/12/2016	04/01/2017	COMPLETED
SE	VASU K M	05/12/2016	04/01/2017	COMPLETED
EE	YARAPPA REDDY	05/12/2016	04/01/2017	COMPLETED
AEE	SHIVAKUMAR	05/12/2016	04/01/2017	COMPLETED
AE	MADHAV RAO	05/12/2016	04/01/2017	COMPLETED
AE	MADHAV RAO	05/12/2016	04/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0327, W0274, I0246, W0331